

**To:** Ryan Rupp[Ryan.rupp@millelacsband.com]; Andrew Boyd[Andy.Boyd@millelacsband.com]  
**From:** Restaino, Mark  
**Sent:** Wed 9/9/2015 2:46:38 PM  
**Subject:** FW: Morning Star Market  
[DMOil.pdf](#)

Here is an email I received from Rich Mycue. It appears that the USTs are manifolded together with a siphon bar. He provided an updated cathodic protection test showing that that siphon bar was tested. From what I can tell this test looks okay.

Now that we know the tanks are manifolded I need more information regarding the ATG. I will follow-up shortly with an email to Rich and copy you.

-Mark

**From:** Rich Mycue [mailto:rmycue@dmoilmn.com]  
**Sent:** Friday, September 04, 2015 10:54 AM  
**To:** Restaino, Mark  
**Subject:** Morning Star Market

Mark;

Attached is the test results for Morning Star Market ;

The tanks and lines including the syphon pipe between the tanks; also the ATG is set to test the tanks at 51 % ; I believe that is what we needed to cover;

Anything else please call me ?

I wasn't able send this email to either Andy or Ryan their address kept getting kicked back;

Thank You

Rich Mycue

D&M Oil Co.- Eggens Direct Service;

P.O. Box 115

Milaca , Mn. 56353

Office: 877-983-3761

Direct: 320-983-2057

Fax: 320-983-3083

Cell: 612-390-6592

Email: [rmycue@dmoilmn.com](mailto:rmycue@dmoilmn.com)

**From:** DM Oil Scanner [<mailto:eggensscan@dmoilmn.com>]

**Sent:** Friday, September 04, 2015 5:31 AM

**To:** Rich Mycue

**Subject:**

